

## FIG. 1




FIG. 2

T052410 "85562860





FIG. 3



TOP SECRET - 835355240

4/17

PU01-0167  
EP01-0167  
PCN01-0167

FIG. 4 A




FIG. 4 B





FIG. 5






FIG. 6

FIG. 7 A

ENGINE START




FIG. 7 B




FIG. 8






FIG. 10



**FIG. 9A**

ENGINE START

**FIG. 9B**

ACC

(252)

IG

(253)

ST

(254)

SL

(251)

SL

(V)

SL

(IV)

(III)

(II)

(I)

HDD ACTIVATION

**FIG. 9C**

ACC

(252)

IG

(253)

ST

(254)

SL

(251)

SL

(V)

SL

(IV)

(III)

(II)

(I)

HDD ACTIVATION

**FIG. 9D**

ACC

(252)

IG

(253)

ST

(254)

SL

(251)

SL

(V)

SL

(IV)

(III)

(II)

(I)

HDD ACTIVATION



**FIG. 11**

FIG. 12



FD0E2410 "8556E260

FIG . 13 A





FIG . 13 B



TUE 24/10 09:56:36.0

FIG. 14 A

ENGINE START

ACC ON ST





FIG. 14 B

ACC  
(252)

BACKUP POWER SUPPLY

(251)



T052H0 "8E55E850

FIG. 15 A




FIG. 15 B




FIG. 16 A

BACKUP POWER SUPPLY

ACC ON ST ENGINE START

(251)




FIG. 16 B

ACC (252)




FIG. 17-360

16/17

PU01-0167  
EP01-0167  
PCN01-0167




FIG. 18A



FIG. 18 B




FIG. 18C



FIG. 18 D